

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

PAT MCCRORY
GOVERNOR

ANTHONY J. TATA
SECRETARY

February 18, 2014

MEMORANDUM TO: Undrea J. Major

Project Development Engineer

Project Development – Western Region/Turnpike

FROM: Terry W. Fox, LG

GeoEnvironmental Project Manager

GeoEnvironmental Section Geotechnical Engineering Unit

TIP NO: I-4400 / I-4700 WBS: 34232.1.1

COUNTY: Henderson-Buncombe

DIVISION 14

DESCRIPTION: I-26 from NC 225 (US 52 Connector) to NC 280 in Henderson &

Buncombe Counties

SUBJECT: GeoEnvironmental Report for Planning

The GeoEnvironmental Section has completed the GeoEnvironmental Report for Planning. This report has the following components and is transmitted as:

_X Hazardous Materials Report (30) pages

Please contact me if you have any questions concerning this project.

Hazardous Materials Report

The GeoEnvironmental Section of the Geotechnical Engineering Unit has investigated the above referenced project to identify hazardous material sites for inclusion in the environmental document.

HAZARDOUS MATERIALS EVALUATION

Purpose

This section presents the results of a hazardous material evaluation conducted along the above referenced project. The main purpose of this investigation is to identify properties within the project study area that are or may be contaminated and therefore result in increased project costs and future liability if acquired by the Department. Hazardous material impacts may include, but are not limited to, active and abandoned underground storage tank (UST) sites, hazardous waste sites, regulated landfills and unregulated dumpsites.

Techniques/Methodologies

The Geographical Information System (GIS) was consulted to identify known sites of concern in relation to the project corridor. GeoEnvironmental Section personnel conducted an initial field reconnaissance along the entire above mentioned project on May 17 and 18, 2006. Additional surveys were conducted at interchanges within the project corridor on July 19, 2010, June 12, 2012, November 26, 2012 and February 5, 2014. An updated search of appropriate environmental agencies' databases and Sanborn Maps was performed to assist in evaluating sites identified during this study.

Findings

UST Facilities

Based on our study, seventeen (20) sites may contain petroleum USTs within the project limits.

Hazardous Waste Sites

No Hazardous Waste Site was identified within the project limits.

Landfills

Two (2) apparent landfills were identified within the project limits.

Other GeoEnvironmental Concerns

No other geoenvironmental concerns were identified within the project limits.

Anticipated Impacts

Seventeen (17) possible UST facilities and two (2) landfills were identified within the proposed project limits. We anticipate low monetary and scheduling impacts resulting from these sites. (See the following table and appendices for details)

Known and Potential Hazardous Material Sites

1) **Property Name**

Energy Mart Store 8 101 Commercial Blvd Flat Rock, NC 28731

Facility ID #: 0-035277

Property Owner: T.I.P. #: R-4430

Duane & Margaret McKibbin Family Ltd Partners 745 Ashe Street

Hendersonville, NC 28792

UST Owner:

Henderson Oil Co, Inc. 745 Ash Street

Henderson, NC 28792



This gas station, convenience store and McDonald's restaurant is located in the southwest quadrant of I-26 between Upward Road and Commercial Boulevard. According to the UST Section Registry there are four (4) tanks currently in use. No ground water incidents are associated with this facility. **This site** is anticipated to present low geoenvironmental impacts to the project. Sites 1-3 were investigated, and a Hazardous Materials Report was submitted under T.I.P. # R-4430. This parcel was not impacted by the Upward Road widening.

Mountain Energy 25 712 Upward Road Flat Rock, NC 28731

Facility ID #: 0-009804 Incident #: 19386, 12892 Property Owner: T.I.P. #: R-4430

Anne E. Dyer 941 Morningside Drive Johnson City, TN 37604

UST Owner:

Mountain Energy Corp.

PO Box 1050

Asheville, NC 28802



This active Shell gas station and convenience store is located in the northwest quadrant of I-26 and Upward Road intersection. According to the UST Section Registry there are three (3) tanks currently in use. Seven (7) tanks were removed in 1994 and two (2) additional tanks were removed in 1998. Ground Water Incident 12892 was assigned to Norm's Mini Mart, the original facility owner in 1994. There are monitoring wells on and public water cannot cross this property. A second UST leak incident, 19386 was reported in 1998 and closed out the same year. This site is anticipated to present low geoenvironmental impacts to the project. Two monitoring wells were abandoned by the GeoEnvironmental Section under T.I.P. # R-4430. The remaining parcel was not impacted by the Upward Road widening.

Four Seasons Triangle 215 754 Upward Road Flat Rock, NC 28731

Facility ID #: 0-035376

Property Owner: T.I.P. #: R-4430

J. Hall Waddell PO Box 629 Hendersonville, NC 28793

UST Owner:

J.H. Reaben Oil & Supply Co, Inc. PO Box 629 Hendersonville, NC 28793



This active Marathon gas station and convenience store is located in the southeast quadrant of I-26 and Upward Road intersection. According to the UST Section Registry there are four (4) tanks currently in use. No ground water incidents are associated with this facility. **This site is anticipated to present low geoenvironmental impacts to the project.** This parcel was not impacted by the Upward Road widening.

Energy Mart 1 1920 Four Seasons Blvd Hendersonville, NC 28792

Facility ID #: 0-017523

Incident #: 28563, 9644, 9280, 9257

Property Owner:

Duane & Margaret McKibbin Family Ltd Partners 745 Ashe Street Hendersonville, NC 28792

UST Owner:

Henderson Oil Co, Inc. 745 Ash Street

Henderson, NC 28792



This active Exxon gas station convenience store is located in the south quadrant of Four Seasons Boulevard and Orrs Camp Road intersection. According to the UST Section Registry there are three (3) tanks currently in use. One (1) tank was removed in 2007. Ground Water Incidents 9280 and 9257 were closed out in 1992. Incident 9644 was assigned when free product was detected on site. This incident was closed out in 2010. Incident 28563 was assigned to this facility in 2007 when minor soil contamination was found. A No Further Action letter was issued the same year. **This site is anticipated to present low geoenvironmental impacts to the project.**

Hendersonville Tire Co. 20 Francis Road Hendersonville, NC 28792

Facility ID #: N/A

Property Owner:

JCPSMP Properties, LLC 575 Jackson Road Fletcher, NC 28732

UST Owner:

JCPSMP Properties, LLC 575 Jackson Road Fletcher, NC 28732



This tire store is located in the northeast side of Francis Road and 300 feet west of the Chimney Rock Road intersection. According to the owner, Jim Parham, a UST was removed in 1985. There is no record in the UST Section Registry. A waste oil UST is located at the rear of the main structure. No ground water incidents are associated with this facility. **This site is anticipated to present low geoenvironmental impacts to the project.**

Stop N Go 2 103 Sugarloaf Road Hendersonville, NC 28792

Facility ID #: 0-009807

Property Owner:

Mian Real Estate, LLC

PO Box 461

Fletcher, NC 28732

UST Owner:

Mian, LLC PO Box 461

Fletcher, NC 28732



This active Shell gas station and convenience store is located in the southwest quadrant of Chimney Rock Road and Sugar Loaf Road intersection. According to the UST Section Registry there are five (5) tanks currently in use. Eight (8) tanks were removed in 1993. No ground water incidents are associated with this facility. This site is anticipated to present low geoenvironmental impacts to the project.

Interstate Express Lube 104 Sugarloaf Road Hendersonville, NC 28792

Facility ID #: 0-009485 Incident #: 19292

Property Owner:

Jerry & LaRue Laughter 184 Refreshing Ridge Hendersonville, NC 28792

UST Owner:

Cason Companies, Inc. 203 West King Street East Flat Rock, NC 28726



This active Sunoco gas station and convenience store is located in the east side of Sugar Loaf Road and 250 feet south of the Chimney Rock Road intersection. According to the UST Section Registry there are five (5) tanks currently in use. Three (3) tanks were removed in 2000. Two (2) tanks owned by Friendly City were removed in 1991 and 1995. Ground Water Incident 19292 was assigned to this facility in 1998 after a small diesel spill. The incident was changed to 'low risk' in 2008. **This site is anticipated to present low geoenvironmental impacts to the project.**

Sam's Club 4950 53 Highlands Square Drive Hendersonville, NC 28792

Facility ID #: 0-036328 Incident #: 28452

Property Owner:

Walmart Real Estate Business Trust 2001 SE 10th St Bentonville, AR 72712

UST Owner:

Sam's East, Inc. 702 SW 8th Street Bentonville, AR 72716



This active Sam's Club gas station is located on the west quadrant of Chimney Rock Road southbound and Highlands Square Drive intersection. According to the UST Section Registry there are four (4) tanks currently in use. Ground water incident 28452 was assigned to the former UST owners, Murphy USA Marketing in 2006. Sam's East (Walmart) conducted a PSA, an LSA and repaired the USTs. The incident was closed out in 2007. **This site is anticipated to present low geoenvironmental impacts to the project.**

Four Seasons Triangle 209 2545 Chimney Rock Road Hendersonville, NC 28792

Facility ID #: 0-010251

Property Owner:

Sonja Waddell PO Box 629 Hendersonville, NC 28793

UST Owner:

J.H. Reaben Oil & Supply Co., Inc. PO Box 629 Hendersonville, NC 28793



This active Marathon gas station and convenience store is located between Chimney Rock Roads, both northbound and southbound, and north of Highlands Square Drive intersection. According to the UST Section Registry there are five (5) tanks currently in use. No ground water incidents are associated with this facility. This site is anticipated to present low geoenvironmental impacts to the project.

Discount Convenience Store 5 5829 Ashville Hwy Hendersonville, NC 28791

Facility ID #: 0-035974

Property Owner:

Vann Properties, LLC 63 Stone Hollow Road Fletcher, NC 28732

UST Owner:

Mansfield Oil Co of Gainesville 1025 Airport Parkway SW Gainesville, GA 30501



This active Citgo gas station and convenience store is located on the southwest side of Asheville Highway and south of the Cureton Place intersection. According to the UST Section Registry there are four (4) tanks currently in use. No ground water incidents are associated with this facility. **This site is anticipated to present low geoenvironmental impacts to the project.**

R&P Cycle Supply 5858 Asheville Hwy Hendersonville, NC 28791

Facility ID #: 0-009741 Incident #: 24239, 07339

Property Owner:

Ronnie Gray 238 Hyder View Drive Hendersonville, NC 28791

UST Owner:

Petroleum World, Inc.

681 NC 120

Mooresboro, NC 28114



This former gas station (Hudson's Chevron) is located on the northeast side of Asheville Highway and across from the Cureton Place intersection. According to the UST Section Registry there is one (1) 500 gallon tank currently in use. Five (5) tanks were removed in 2004. Ground Water Incident 24239 was assigned to this facility and free product is still present in the groundwater and the site is under remediation. **This site is anticipated to present low geoenvironmental impacts to the project.**

Exxon Travel Plaza 5990 Asheville Hwy Hendersonville, NC 28791


Facility ID #: 0-032376

Property Owner: NCDOT Parcel 19

Mary & Nteimam Jonathan 31804 Thornhill Place Abbotsford, BC V2T6Y3

UST Owner:

I-S-I Enterprises, LLC 149 Keystone Drive Asheville, NC 28806



This vacant gas station convenience store is located in the southeast quadrant of I-26 and Asheville Highway. According to the UST Section Registry there are three (3) tanks currently in place. No ground water incidents are associated with this facility. **This site is anticipated to present low geoenvironmental impacts to the project.**

Apple Tree Honda I-26 @ Airport Road/195 Underwood Fletcher, NC 28732

Facility ID #: 0-003618 Incident #: 19727

Property Owner: T.I.P. #: I-5501

Krafton Locke Enterprises, LLC 195 Underwood Road Fletcher, NC 28732

UST Owner:

Apple Tree Enterprises 195 Underwood Road Fletcher, NC 28732



This automotive dealership is located south of Underwood Road and east of I-26. According to the UST Section Registry two (2) tanks were removed in 1998. Ground Water Incident 19727 was assigned to this facility in 1998. The incident was closed out in 1999. **This site is anticipated to present low geoenvironmental impacts to the project.** This interchange was investigated and a Hazardous Materials Report was submitted under **T.I.P.** # **I-5501**. Sites 11, 12 and 13 were outside the I-5501 project limits.

Mr. Pete's Market 2 653 New Airport Road Fletcher, NC 28732

Facility ID #: 0-013168 Incident/ UST #: AS-2940 Property Owner: T.I.P. #: I-5501

Youngblood Oil Co., Inc.

PO Box 2590

Hendersonville, NC 28793

UST Owner:

Youngblood Oil Co., Inc.

PO Box 2590

Hendersonville, NC 28793



This active BP gas station and convenience store is located on the east side of New Airport Road and across from the Asheville Regional Airport entrance. According to the UST Section Registry there are four (4) tanks currently in use. Six (6) tanks were removed in 1990. One (1) tank was removed in 1997 and Ground Water Incident/ UST # AS-2940 was assigned to this facility. The incident was closed out in 1998 as a clean closure. This site is anticipated to present low geoenvironmental impacts to the project.

15) **Property Name**Mountain Energy 1

Mountain Energy 12 443 New Airport Road Arden, NC 28704

Facility ID #: 0-035421

Property Owner: T.I.P. #: I-5501

Brumit Development Group, LLC

PO Box 15726


Asheville, NC 28813

UST Owner:

Mountain Energy Corp.

PO Box 1050

Asheville, NC 28802



This active Shell gas station, convenience store and Arby's Restaurant is located on the southeast quadrant of New Airport Road and Brian Boulevard intersection. According to the UST Section Registry there are two (2) tanks currently in use. No ground water incidents are associated with this facility. This site is anticipated to present low geoenvironmental impacts to the project.

Citizens Food Store 114 377 Long Shoals Road Arden, NC 28716

Facility ID #: 0-031879

Property Owner: T.I.P. #: R-2813B

Superior Properties of Asheville

PO Box 2805

Asheville, NC 28802

UST Owner:

Citizens Fuel Co.

PO Box 2805

Asheville, NC 28802



This former gas station and convenience store is located in the southeast quadrant of NC 146 (Long Shoals Road) and Skyland Inn Drive. The store has been demolished since this photo was taken. According to the UST Section Registry there are four (4) tanks still on site. No ground water incidents are associated with this facility. This site is anticipated to present low geoenvironmental impacts to the project. This property was not impacted by T.I.P. #: R-2813B.

17) **Project**

Energy Mart 10 380 Long Shoals Road Aden, NC 28704

Facility ID #: 0-036325 Incident #: 28625 **Property Owner:** T.I.P. #: R-2813B


Henderson Oil Co, Inc. 745 Ash Street Hendersonville, NC 28792

UST Owner:

Henderson Oil Co, Inc. 745 Ash Street Hendersonville, NC 28792



This active BP gas station and McDonald's Restaurant is located on the northwest quadrant of Long Shoals Road and Schenck Street intersection. According to the UST Section Registry three (3) tanks are currently in use. The NCDOT removed three (3) USTs from this property in June 2008 as part of **T.I.P.** # **R-2813B**. Three (3) older tanks were removed in 2000. Two (2) tanks owned by Friendly City were removed in 1999. Ground Water Incident 28625 was assigned to this facility in 2008 and the incident was closed out the same year. **This site is anticipated to present low geoenvironmental impacts to the project.**



Prescoping investigations for **T.I.P.** # **I-5504** were completed November 26, 2012 and again on February 5, 2014 when the project limits were expanded. The Geotechnical Engineering Unit / GeoEnvironmental Section searched the GIS databases within the given project study area to identify known potential hazardous waste sites. No petroleum sites, hazardous waste sites, apparent landfills, or other geoenvironmental concerns were identified within the project limits,

19) **Property Name**Mountain Metals Recycling
79 Pond Road
Asheville, NC 28806

Property Owner: T.I.P. # B-5178 Sonia G Gribble PO Box 8160 Asheville, NC 28814



This facility currently operates as a recycling center specializing in scrap metal. It is located in the northeast quadrant of SR 3431 (Pond Rd) and I-26 intersection. The center is located on the site of the former Pond Road landfill. The landfill had a municipal solid waste cell, and illegal tire dump, and accepted household hazardous waste. A Brownfields Agreement is under negotiation. This site is anticipated to present low to moderate geoenvironmental impacts to the project. Sites 15-18 were investigated, and a Hazardous Materials Report was submitted under T.I.P. # B-5178.

Southern Concrete Materials Inc. 80 Pond Road Asheville, NC 28806

Facility ID #: 0-036323

Property Owner: T.I.P. # B-5178

Southern Concrete Materials Inc.

PO Box 5395

Asheville, NC 28813

UST Owner:

Southern Concrete Materials Inc.

PO Box 5395

Asheville, NC 28813



This facility currently operates as a ready-mix concrete and concrete products supplier. It is located in the southeast quadrant of SR 3431 (Pond Rd) and I-26 intersection. The operation is also located on the site of the former Pond Road landfill. The site has been built up using a concrete block retaining wall and filled in with gravel. According to the UST Section registry there is one (1) tank currently in use and was installed in 2001. This site does not appear on the Ground Water Incident database. **This site is anticipated to present low geoenvironmental impacts to the project.**

21) **Property Name**JMJ Tomato Properties LLC
99 Pond Road
Asheville, NC 28806

Property Owner: T.I.P. # B-5178 JMJ Tomato Properties LLC PO Box 16528 Asheville, NC 28816



This facility currently operates as a produce distributor and warehouse. A number of businesses have operated at this location including Plasticard and Quaker Oats. It is located in the northwest quadrant of SR 3431 (Pond Rd) and I-26 intersection. There is the possibility that this may have been the site of a gas station. There are no monitoring wells on site. There is a concrete pad in the middle of the asphalt parking area. This site does not appear on the UST Section registry. **This site is anticipated to present low geoenvironmental impacts to the project.**

22) **Property Name**Henson's, Inc. Mulch & More
116 Pond Road
Asheville, NC 28806

Property Owner: T.I.P. # B-5178 Murmax, LLC PO Box 1276 Columbus, NC 28722



This facility currently operates as a supplier of landscaping material and recycles municipal and industrial yard waste. It is located in the southwest quadrant of SR 3431 (Pond Rd) and I-26 intersection. According to the manager, construction debris is found at the rear of the property and adjacent to the I-26 Right of Way. The Ruckman family previously owned this parcel and the debris was most likely generated from the Ruckman Brothers Construction business. This site does not appear on the UST Section registry. **This site is anticipated to present low geoenvironmental impacts to the project.**

WBS # 34232.1.1 T.I.P.#: I-4400 / I-4700 Page 24 of 24

Please note that discovery of additional sites not recorded by regulatory agencies and not reasonably discernible during the project reconnaissance may occur. The GeoEnvironmental Section should be notified immediately after discovery of such sites so their potential impact(s) may be assessed.

If there are questions regarding the geoenvironmental issues, please contact me, at 919-707-6870.

Terry W. Fox, LG GeoEnvironmental Project Manager


Jew Wox

GeoEnvironmental Section


Geotechnical Engineering Unit

cc:


John Pilipchuk, LG, PE, State Geotechnical Engineer David Chang, Ph. D, PE, State Hydraulics Engineer Charles Brown, PE, PLS, State Locations and Surveys Engineer Tom Koch, PE, Assistant State Structures Engineer Jay Bennett, PE, State Roadway Design Engineer Brian Burch, PE, Area Roadway Construction Engineer Cameron Cochran, PE, Area Bridge Construction Engineer Teddy Greene, Division Right of Way Agent Eric Williams, PE, Geotechnical Regional Manager Jody Kuhne, LG, PE, Regional Geological Engineer Dennis Li, Ph. D, LG, Production Support Supervisor File



Appendix A (Map 5 of 6) Location of USTs, landfills & Other Potentially Contaminated Sites



Appendix A (Map 4 of 6) Location of USTs, landfills & Other Potentially Contaminated Sites



Appendix A (Map 3 of 6)
Location of USTs, landfills & Other Potentially Contaminated Sites

